

PTO Clutch (Gravelv 09225400) Stens

Produkt



STENS produktbeskrivelse:

- Cool Coil Technology
- Does not fit all applications - Verify part number by referring to model specifications
- For mower side wiring harness purchase XMC1003
- High performance bearings with high temperature grease
- Replaceable Pulley Bearing
- Stainless steel rivets and bands
- Super Smooth "Xtreme Precision" Machined Pulley
- To prevent premature clutch failure, follow the instruction sheet included with the clutch
- 1/2" or 5/8"
- 1 1/8"
- Clutch side integrated, water tight and impact resistant wire harness
- 5 3/8"
- Counter Clockwise

StensDimensjoner

Produsentens merkevare	Xtreme
GTIN-nummer	023899567027
Relatert produkt	XMC1003
OEM-nummer	Ariens: 092254, 09225400, 592003, 59200300. AYP: 128711, 539128711. Country Clipper: E-6247, E-6338. Craftsman: 128711, 539128711. Dixon: 128711, 539128711, 539129864, 539129872, 60473, 60499, 61516. Electrolux: 128711, 539128711. Exmark: 94-6136. Gravelv: 092026, 092080, 092254, 09225400, 592003, 59200300. Husqvarna: 128711, 539128711. Kees: 128711, 539128711. Massey Ferguson: 128711, 539128711. McCulloch: 128711, 539128711. Poulan: 128711, 539128711. Toro: 94-6136. Warner: 5218-10, 5218-103, 5218-223, 5218-224
Produsentinformasjon	Use with XMC1003 Wire Harness Repair Kit
Lengde	260.0 mm

Høyde	184.0 mm
-------	----------

Bredde	241.0 mm
--------	----------

Vekt	5.9 kg
------	--------

Les mer om produktet her:

<https://www.ariens.no/product?number=X0041>