

## INSULATOR GASKET

Produkt



Insulator Gasket Replaces Honda 16223-ZE3-800 Ethanol: Not compatible with greater than 10% ethanol fuel Ethanol Not compatible with greater than 10% ethanol fuel Honda code 2107902-3795366-4426714 Use with 520-734 Carburetor 520-734 Carburetor, Included in the 785-697 Carburetor Service Kit 785-697 Carburetor Service Kit, Use with 520-738 Carburetor 520-738 Carburetor, Included in the 785-673 Carburetor Service Kit 785-673 Carburetor Service Kit

Ethanol: Not compatible with greater than 10% ethanol fuel Ethanol Not compatible with greater than 10% ethanol fuel Honda code 2107902-3795366-4426714

### Stens

Passer merke	Honda
Relatert produkt	520-734
Varegruppe	Insulator Gasket
Antall pr. artikkel	1 stk
Vekt	1.36077711E-4 Kg
OEM-nummer	Honda 16223-ZE3-000, 16223-ZE3-306, 16223-ZE3-800, 16223-ZE3-W00;
Passer modell	Honda GX340 and GX390
Inkludert i	Use with 520-734 Carburetor 520-734 Carburetor, Included in the 785-697 Carburetor Service Kit 785-697 Carburetor Service Kit, Use with 520-738 Carburetor 520-738 Carburetor, Included in the 785-673 Carburetor Service Kit 785-673 Carburetor Service Kit
Tilleggsinfo	Use with 520-734 Carburetor 520-734 Carburetor, Included in the 785-697 Carburetor Service Kit 785-697 Carburetor Service Kit, Use with 520-738 Carburetor 520-738 Carburetor, Included in the 785-673 Carburetor Service Kit 785-673 Carburetor Service Kit
Delenummer	266-4305 5407320 IE-0403

## konkurrenter

**Cross Sell** 520-734, 785-697, 520-738, 785-673

**Up Sell** Use with 520-734 Carburetor 520-734 Carburetor, Included in the 785-697 Carburetor Service Kit 785-697 Carburetor Service Kit,  
Use with 520-738 Carburetor 520-738 Carburetor, Included in the 785-673 Carburetor Service Kit 785-673 Carburetor Service Kit

Les mer om produktet her:

<https://www.ariens.no/product?number=485-403>