


IGNITION COIL

Produkt



Ignition Coil Replaces Honda 30500-ZJ1-845 Verify OEM part number by referring to engine model and spec - does not fit all applications Verify OEM part number by referring to engine model and spec - does not fit all applications Right Honda code 8678609 Use with 131-039 Spark Plug 131-039 Spark Plug, Use with 130-823 Spark Plug 130-823 Spark Plug

Verify OEM part number by referring to engine model and spec - does not fit all applications Verify OEM part number by referring to engine model and spec - does not fit all applications Right Honda code 8678609

Ariens DelerStens

GTIN	2.3899299492E10
Passer merke	Honda
Relatert produkt	130-823
Varegruppe	Ignition Coil
Antall pr. artikkel	1 stk
Vekt	0.30390688790000003 Kg
OEM-nr	Honda 30500-ZJ1-841, 30500-ZJ1-842, 30500-ZJ1-843, 30500-ZJ1-844, 30500-ZJ1-845;
Passer modell	Honda GX610, GX620 and GX670
Inkludert i	Use with 131-039 Spark Plug 131-039 Spark Plug, Use with 130-823 Spark Plug 130-823 Spark Plug
Tilleggsinfo	Use with 131-039 Spark Plug 131-039 Spark Plug, Use with 130-823 Spark Plug 130-823 Spark Plug
Delenummer konkurrenter	16147 2609643 263-3481 IG-0121
Cross Sell	131-039, 130-823
Up Sell	Use with 131-039 Spark Plug 131-039 Spark Plug, Use with 130-823 Spark Plug 130-823 Spark Plug

Les mer om produktet her:

<https://www.ariens.no/product?number=440-121>